

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

### Inspection Report Minerals Regulatory Program

March 14, 2011

	1
Reviewed:	

Mine Name: Ticaboo Stockpile Removal Project	Permit Number: S/017/0001			
Operator Name: Ucolo Exploration Company	Inspection Date: December 1, 2010			
Inspector(s): Paul Baker and Tom Munson	Time: about 2:00 PM			
Other Participants: None	Mine Status: Inactive			
Elements of Inspection	Evaluated	Comment	Enforcement	
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> </ol>				

1.	Permits, Revisions, Transfer, Bonds		$\boxtimes$	
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
	Protection of Drainages / Erosion Control	$\boxtimes$	$\boxtimes$	
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
	Reclamation			П
7.	Backfilling/Grading (trenches, pits, roads, highwalls,			
	Soils			n
9.	Revegetation			П

## Purpose of Inspection:

10. Other

The area had had a substantial rainstorm, and we wanted to check whether there had been damage to the berm around the stockpile.

#### **Inspection Summary:**

1. Permits, Revisions, Transfer, Bonds

The Division holds a reclamation surety of \$6000.00 in the form of a certificate of deposit which is due for escalation in November 2011. The permit fee is up to date.

#### 3. Protection of Drainages / Erosion Control

There has been a fair amount of erosion off the stockpile, but I only saw one place where the berm had breached.

#### **Conclusions and Recommendations:**

The berm needs to be repaired, and I recommend that the ditch on the inside of the berm be cleaned out so it is ready for runoff from the next storm.

Inspector's Signature

PBB:eb

cc: sfivecoat@blm.gov, wstokes@utah.go

Loree Gregg

O:\M017-Garfield\M0170001-TicabooStockpileRemoval\inspection\ins-12012010.doc

Inspection Date: December 1, 2011; Report Date: March 14, 2011

Page 2 of 2 S/049/0001



Photo 1. The area inside the berm has a fair amount of sediment that should be cleaned out.



Photo 2. Breached berm.



Photo 3. Erosion coming off the stockpile.